
Fig. 1



2/11

Fig. 2






Fig. 3



WO 2005/067589 PCT/US2005/000217




5/11


Fig. 5


Formatted VendorlGsm Record


	RecordDescriptor	[8] : [01780000]
501 ~	Hexadecimalid	(2): laal
	MscStructureCode	(6): [10003] (Mobile Terminated Call
	CallTypeCode	(4) : [002] (Mobile Terminated)
	StudyIndicator	(2) : [0] (Normal Record)
	CallForwardIndicator	(2):[1]
	CalledParty	(30) : [1-210888888822076]
502	CallingNumber	(30) : [0-01201-21088888888]
302	CalledNumber	(40) : [2-01101-12104899999]
_	CalledEquipment	(22) : [350314000942630]
	Additionalinfo	[4]: []
	ChannelAllocationTime	(16) : [031111:15:52:14.700]
~		[16] : [031111:15:52:35.600]
503 ₹	AnswerTime	(16) : [031111:15:52:48.300]
, see	DisconnectTime	(16): [031111:15:52:48.500]
	ReleaseTime	(2):[0]
	OffAirCallSetup	(2) : [0]
504 ~	HalfRateInuse	(4): [000] (Normal Release)
304	– CauseForTermination	
505 ~	CallReference	(8): [0250762]
	MsClassMark	(8): [2100100]
	ClassMarkTimeStamp	(16) : [031111155212500]
	IncomingTrunkGroup	(6) : [00211]
	IncomingTrunkMember	[6] : [00071]
	IncomingRouteGroup	(4):
	TrunkSeizureTimeIncoming	(16) : [031111155210100]
	CallingSuscriberCategory	(4): [010] (Ordinary)
	Callindicator	(8): [0000000] (No Indication)
	CaliDuration	(8): [0000013]
	Diagnostic	(6) : [04016]
	MscNumber	(28): 01101-19078319014
	RecordNumber	(12) : [00294173267]
	*** Appended module ***	
		(() [0.00]
	MscModuleCode03	(4): [003]
	RoamingNumberAp03	(30): [3-01101-16264281054]
	MscNumberAp03	(28) : [01101-19078319014]
-00	IncomingTrunkGroupAp03	(6): [00552]
	IncomingTrunkMemberAp03	(6): [00010]
	LocationAreaAp03	(12) : [31038005030]
506 ~	CeilldentityAp03	(6) : [04761]
	ChannelType	(6) : [11120]



WO 2005/067589 PCT/US2005/000217







WO 2005/067589 PCT/US2005/000217

10/11

Fig. 10

